
REPARATII POMPA FLYGT 8.9 KW

I.D.: 50265075

Data publicarii	02.10.20	Coduri CPV	50511000-0
Pretul estimativ:	1.550,00 RON - 1.550,00 RON		
Descriere:	REPARATII POMPA FLYGT 8,9 KW -Rebobinat ; -Lucrari mecanice conexe ; -Inlocuire rulmenti ; -Completare ulei		
