
Reparatie pompa TP 28M10/2D

I.D.: 41130558

Data publicarii	09.01.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ:	1.769,00 RON - 1.769,00 RON
-------------------	-----------------------------

Descriere:	Reparatie pompa ce consta in inlocuire: Kit etansare mecanica; Kit rulmenti; Kit inele "O"; Vaselina; Ulei
------------	--
