
Service aer conditionat tip chiller Clint

I.D.: 61288087

Data publicarii	23.09.21	Coduri CPV	50730000-1
-----------------	----------	------------	------------

Pretul estimativ: 417,00 RON - 417,00 RON

Descriere: Service aer conditionat la echipament preparare apa racita tip chiller Clint. - Constatate defectiune chiller Clint - Realizare interventie service - Sigurante fuzibile rapide 10x38-16A
