
Muzeul National Brukenthal

I.D.: 58430253

Data publicarii	30.06.21	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 784,74 RON - 784,74 RON

Descriere: 1.Facilitare a miscarii etrierelor de frana si pistoanelor fata (punte fata) 2. Verificare sistem de aer conditionat 3. Reparare compresor aer conditionat 4. VERIFICARE GENERALA 5 .POLISAT FARURI 6.Bobina. ambreiaj magnetic compresor 7. FREON R134A
