
Reparat POMPA WILO 4.8KW/3000T

I.D.: 45979113

Data publicarii	29.04.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ:	2.510,00 RON - 2.510,00 RON
-------------------	-----------------------------

Descriere:	demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansari mecanice, reparat cablu alimentare +ulei siliconic
------------	--
