

---

## SERVICII DE REPARARE AUTO TM 10 XBK

I.D.: 86227853

---

Data publicarii	21.08.23	Coduri CPV	50112100-4
-----------------	----------	------------	------------

---

Pretul estimativ:	306,07 RON - 306,07 RON
-------------------	-------------------------

---

Descriere:	Reparatie auto Dacia Duster, 1.5 DCi, TM10 XBK, inlocuire rezistenta aer conditionat incluzand si montajul.
------------	---

---