

## reparatii curente primarie si drum

I.D.: 52659809

---

Data publicarii	14.12.20	Coduri CPV	44190000-8
-----------------	----------	------------	------------

---

Pretul estimativ: 7.571,43 RON - 7.571,43 RON

---

Descriere: sort-2, nisip-2, robinet dublu servici 3/4-buc, cleste cuie-1buc, banda teflon-1 buc, cot comp.40mm-1 buc, cot comp 25-3/4fi-1buc, racord comp.40-114fi-1buc, racord comp 25-3/4fe-1buc, banda acoperire-1buc, red.zn 11/4-3/4-1buc, tub pe 40mm-1m, tub pe 25mm-2m, robinet dublu servici 3/4-2buc, teu comp 25mm-2buc, mufa pr 25mm-1buc, cot comp 25-3/4-2buc, mops suedez 1,5-1buc, tub pe 25mm-3buc, plase-1buc, sort 2.5mc, nisip 2.5mc, ciment 10saci, rezervor 1000l cu grilaj-1buc, betoniera 160l-1buc, electrozi supertit fin-4.5kg, panouy gard zn 2500x1700-7buc, holsurub rigips 3.5x35--300buc, holsurub rigips 3.5x45-300buc, placi osb 15-7buc, placi rigips baie-7 buc, grinzi rasinoase -0.72mc,sifon pardoseala-1buc, inaltator inox-1buc, mufa pvc d.50mm-4buc, ramif pvc 50-87--4buc, dop pvc 110mm-2buc, cot pvc 50-90-6buc, cot pvc 50-45-6buc, cot pvc 110-87-5buc, ramif.110-50-45-4buc, ramif pvc 110-87-1buc, reductie pvc 110-50-1buc, tub pvc 50-12ml, tub pvc.110x2000-6buc, ramif.pvc.160-87-1buc, reductie pvc 160-110-1buc, mufa pvc 160-1buc, lubrifiant multifunctional-1buc, adeziv cm17-2kg-2buc, tub pvc 110x2000-3buc, tub pvc 500-2buc.

---