
Service Dacia Dokker BC 15 DPP.

I.D.: 79663301

Data publicarii	09.03.23	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ:	931,10 RON - 931,10 RON
-------------------	-------------------------

Descriere:	Inlocuit .conducta aer, reparat instalatie electrica Dacia Dokker 1.5DCI.
------------	---
