

Reparatie aparat electroterapie BTL 5620

I.D.: 73663443

Data publicarii	27.09.22	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 1.350,00 RON - 1.350,00 RON

Descriere: 1) Placa encoder VN v.300 - 1000,00 ron 2) Manopera aferenta constatare/diagnosticare/reparatie - 350,00 ron COMANDA SEAP TINE LOC DE COMANDA FERMA!
