

Servicii reparatie - VW Transporter MAI 34848

I.D.: 39769898

Data publicarii	16.05.18	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 1.411,76 RON - 1.411,76 RON

Descriere: Servicii reparatie - VW Transporter MAI 34848 - inlocuire rulmenti butuc roata stg / dr fata si flanse amortizor fata CONFORM ANUNT PUBLICITAR ADV1009327
