

Reparatie switch, reparatie multifunctional laser

I.D.: 55918949

Data publicarii 08.04.21 Coduri CPV 50800000-3 50000000-5

Pretul estimativ: 170,00 RON - 170,00 RON

Descriere: Diverse servicii de intretinere si de reparare, reparatie sursa switch, reparatie , curatire, inlocuire piese defecte multifunctional Kyocera Ecosys M2035DN.
