

---

## **Reparatie Videocolonoscop Pentax MODEL: EC-3890FK2/K120254**

I.D.: 98037732

---

Data publicarii 31.05.24

Coduri CPV 50420000-5

---

Pretul estimativ: 20.880,00 RON - 20.880,00 RON

---

Descriere: Cod / Nr. crt. Denumire Cantitate Preț unitar Preț total D892-U5015-1 DISTAL END ASSY WITH TUBES 1 7543 7543 D013-SA011-B1 BENDING RUBBER 1 209 209 D014-AA037 ANGLE WIRE 4 171 648 MX00-S2322 ADJUSTING COLLAR 4 40 160 D756-SA057-2 ROOT BRACE RUBBER IMP-1 1 427 427 D201-U2165 RL PULLEY ASSY 1 1535 1535 D201-U2160 UD PULLEY ASSY 1 1535 1535 D756-SB308 ROOT BRACE RUBBER LG BODY 1 565 565 MX00-A2469 LIGHT GUIDE FIBER BUNDLE(LCB) 1 7828 7828 10 Set garnituri etansare 1 265 265 11 Adezivi, consumabile diverse 1 165 165 TOTAL fara TVA 20880,00 LEI TOTAL cu TVA 24847.20 LEI

---