
Servicii de reparatie masina gatit Studiocasa

I.D.: 35973981

Data publicarii	17.05.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	441,13 RON - 441,13 RON
-------------------	-------------------------

Descriere:	Inlocuire termocupla cuptor,termocuple arzatoare superioare ,manopera
------------	---
