

Serviciu de reparare RICOH MP2501

I.D.: 83551132

Data publicarii 14.06.23 Coduri CPV 50313100-3

Pretul estimativ: 2.859,60 RON - 2.859,60 RON

Descriere: 1 B0399510 OPC DRUM 1 228.50 2 AD027018 CHARGE ROLLER 1 222.24 3 AD042058 CHARGE CLEANER BRUSH ROLLER 1 108.24 4 AD042083 CLEANING BLADE 1 84.38 5 B0393060 DEVELOPMENT ROLLER GEAR 1 20.23 6 B0393062 IDLER GEAR 16Z 1 42.02 7 B0392335 PICKOFF PAWLS 2 211.84 8 D1589640 DEVELOPER K 1 169.26 9 D1583820 TRANSFER ROLLER 1 198.12 10 D1584174 Plain Shaft Bearing Press roller 2 19.80 11 D1584043 STRIPPER PAWLS (MP2501) 5 69.20 12 AE011145 Hot roller 1 368.78 13 G0524618 BEARING 30X42X7 2 119.92 14 AE020258 PRESSURE ROLLER:MM25 1 336.11 15 AW100073 Thermistor 2 63.56 16 MANOPERA 3 597.40