
Servicii reparare masina spalat pardoseli Karcher B40 BpPack, Sala de sport Giroc, jud. Timis

I.D.: 68379723

Data publicarii	19.04.22	Coduri CPV	98390000-3 98300000-6
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.189,00 RON - 1.189,00 RON

Descriere: Se solicita repararea masinii de spalat pardoseli Karcher B40BpPack utilizata in cadrul Salii de posrt Giroc, respectiv inlocuire buton selectaare programe, cheie galbena, sistem auto-fill-in. Pretul include si manopera.
