
REPARATIE APARAT SUDURA FRIAMAT

I.D.: 77135379

Data publicarii	05.01.23	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.395,31 RON - 1.395,31 RON

Descriere: APROV. PT. SANG. BAI NEC. 28157/ 16.12.2022 REPARATIE APARAT SUDURA FRIAMAT IV BASIC PRINT - seria: FR1767155 Placa control PCB 1x 1245.31 = 1245.31 Manopera = 0.50 x300 = 150 Total 1395.31
