

---

## Servicii reparatie Mitshubishi L200

I.D.: 44858499

---

|                 |          |            |            |
|-----------------|----------|------------|------------|
| Data publicarii | 11.12.19 | Coduri CPV | 50110000-9 |
|-----------------|----------|------------|------------|

---

|                   |                             |
|-------------------|-----------------------------|
| Pretul estimativ: | 3.497,58 RON - 3.497,58 RON |
|-------------------|-----------------------------|

---

Descriere: Inlocuit: pivot, termostat, pompa apa, furtune intrare/iesire racitor ulei, curea A/C, curea pompa apa, intinzator transmisie Piesele necesare pentru reparatie sunt furnizate de service

---