
Reparație tăietor beton asfalt

I.D.: 59958967

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 12.08.21 | Coduri CPV | 98390000-3 50000000-5 |
|-----------------|----------|------------|-----------------------|

Pretul estimativ: 758,82 RON - 758,82 RON

Descriere: REPARATIE TAIETOR BETON ASFALT - REPARATIE TAIETOR BETON ASFALT 1. Cartus filtru aer generator HONDA GX 340 - GX 390 1 buc x 42.02 lei f.t.v.a.. 2. Ulei Motor (4-Timpi) SAE 30 0.6 L 2 buc x 42.02 lei f.t.v.a. 3. Arc Honda GX240, 270, 340 1 buc x 8.40 lei f.t.v.a. 4. Bujie Champion 1 buc x 8.40 lei f.t.v.a. 5. Carburator Honda GX 390 1 buc x 142.86 lei f.t.v.a. 6. SEGMENTI GX 1 buc x 84.03 lei f.t.v.a. 7. Ulei Honda 1 L 10W30S 1 buc x 31.09 f.t.v.a.8. MANOPERA 1 buc x 400.00 f.t.v.a.
