
REPARATIE AMBARCATIUNE RIB

I.D.: 53717821

Data publicarii	26.01.21	Coduri CPV	50241100-7
-----------------	----------	------------	------------

Pretul estimativ: 448,57 RON - 448,57 RON

Descriere: REPARATIE AMBARCATIUNE RIB (MANOPERA MONTAT POMPA SANTINA CU FLOTOR) SI PIESE (POMPA SANTINA - 1 BUC, FLOTOR AUTOMAT - 1 BUC)
