
reparatie sistem tvci

I.D.: 62019228

Data publicarii	13.10.21	Coduri CPV	32323500-8
-----------------	----------	------------	------------

Pretul estimativ: 11.497,90 RON - 11.497,90 RON

Descriere: reparatie sistem TVCI, inlocuire elemente distruse prin supratensiune: XVR 16 canale Dahua buc 1 Camera de supraveghere Dahua 2mp cu microfon incorporat buc 16 Alimentator 12V 2A buc 16 Conector videobalun buc 32 Cablu MYYUP 2x0.75 m 250 Prestari reparatie sistem TVCI , demontare camere de supraveghere defecte, inlocuire cablu, programare si inrolare in sistem TVCI a camerelor de supraveghere noi buc 1
