
REPARATII POMPE

I.D.: 83500808

Data publicarii	13.06.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 4.557,00 RON - 4.557,00 RON

Descriere: REPARATII POMPA WILO CU TOCATOR:rebobinare ; depresat , presat la cald ; REPARATII MIXER SUMERSIBIL FAGGIOLATI SP 2.4 KW:rebobinare ; lucrari mecanice conexe; inlocuire rulmenti+presutupa; REPARATII MIXER SUMERSIBIL FAGGIOLATI SP 2.4 KW:rebobinare; lucrari mecanice conexe ; inlocuire rulmenti ; REPARATII MIXER SUMERSIBIL FAGGIOLATI G272T3T3:rebobinare ; lucrari mecanice conexe; inlocuire presutupe; REPARATII MIXER FLYGT 1.7 KW :rebobinare; inlocuire presutupa;prelucrari mecanice conexe (depresare +presare la cald)
