
Reparatie mixer tip SB1625A45/4.33 motor 5,8 kw/1500rpm

I.D.: 85555557

Data publicarii	04.08.23	Coduri CPV	50511100-1 50532100-4
-----------------	----------	------------	-----------------------

Pretul estimativ:	2.986,00 RON - 2.986,00 RON
-------------------	-----------------------------

Descriere:	Reparatia consta in: demontare, inlocuit: etansari mecanice, inele O, ulei in reductor, rulmenti motor si reductor, montaj, probe
------------	---
