
Reparare si intretinere Mercedes -Benz Sprinter

I.D.: 68833620

Data publicarii	04.05.22	Coduri CPV	50114000-7 50112000-3
-----------------	----------	------------	-----------------------

Pretul estimativ: 360,00 RON - 360,00 RON

Descriere: Reparare la sistemul de evacuare a gazelor si la sistemul de adblue la autospeciala de sonorizare Mercedes -Benz Sprinter A-34556, ss:WDB906637HP337942.
