
servitii tapitat interior auto

I.D.: 100628787

Data publicarii	25.07.24	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ: 4.690,00 RON - 4.690,00 RON

Descriere: Servicii reparare si retapitare Scaun,sezut+spatar BH26SAJ - 1bucx250 ron - 1bucx250 ron
Sezut+spatar BH50SAJ -1bucx250 ron -1bucx250 ron 2 stalpi BH29SAJ -2x120 ron
Scaun,sezut+spatar BH73SAJ -1bucx250 ron -1bucx250 ron Scaun,sezut+spatar BH04SAJ -
1bucx250 ron -1bucx250 ron Scaune BH65SAJ -2buc x250 ron -2buc x250 ron Scaune
complet noi BH17AMB -2buc x600 ron Sezut BH38SAJ -1bucx250 ron
