
Reparatie motopompa Honda WB 20XT

I.D.: 47761388

Data publicarii	02.07.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 159,66 RON - 159,66 RON

Descriere: Conditii neacceptate la termen: Reparatie motopompa Honda WB 20XT-snur demaror - etansare mecanica -ulei -silicon -consumabile -o-ring corp pompa.
