

## Reparatie invertor sudura Arc 180

I.D.: 57348265

---

Data publicarii	25.05.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 42,02 RON - 42,02 RON

---

Descriere: Reparatie invertor sudura Arc 180 , conform deviz atasat: Inlocuit tranzistori IRF9640PBF1066103 - 2 buc Demontat - montat invertor sudura Arc 180

---