
Reparatie aer conditionat Daikin poarta

I.D.: 58423657

Data publicarii	29.06.21	Coduri CPV	50730000-1
-----------------	----------	------------	------------

Pretul estimativ: 6.049,00 RON - 6.049,00 RON

Descriere: - Placa el ectronica main pcb 500626 pentru unitate externa Daikin RMXS 112E8V1B cladire poarta - Display cu led si butoane ... SERVICE PCB 302278P - Capacity adaptor j112 si adaptor condensator 2200 μ F
