

REPARATIE CIOCAN ROTOPERCUTOR MAKITA HR4013C/44 REPARATIE MOTOCOASA MAKITA 4T EBH252U/43

I.D.: 71212410

Data publicarii 11.07.22 Coduri CPV 50800000-3

Pretul estimativ: 1.299,94 RON - 1.299,94 RON

Descriere: RCURI - UZATE, CAPAC + SISTEM PRINDERE - SPARTE, SAIBA + INEL FLOURIDA - UZATE ,
RULMENTI TRANSMISIE + LIMITATOR CUPLU - UZATI 1 625758-6 STATOR BUC 1 132.00 132.00
25.08 2 513888-4 ROTOR BUC 1 301.00 301.00 57.19 3 194160-9 PERII COLECTOARE CB 350
BUC 1 42.02 42.02 7.98 4 211232-6 RULMENT 6002LLU BUC 1 22.37 22.37 4.25 5 211332-2
RULMENT 6004LLU BUC 1 23.48 23.48 4.46 6 213231-4 SIMERING 15 BUC 1 54.79 54.79
10.41 7 213317-4 INEL 20 BUC 2 5.00 10.00 1.90 8 213379-2 INEL CAUCIUC 21 BUC 1 4.00
4.00 0.76 9 213392-0 INEL FLOURIDA BUC 2 48.00 96.00 18.24 10 213406-5 INEL CAUCIUC 30
BUC 3 4.20 12.60 2.39 11 213615-6 INEL CAUCIUC 46 BUC 1 6.26 6.26 1.19 12 213695-2
INEL CAUCIUC 22 BUC 1 39.00 39.00 7.41 13 232180-6 ARC 41 BUC 1 20.54 20.54 3.90 14
233217-2 ARC COMPRESIE 51 BUC 1 11.00 11.00 2.09 15 233218-0 ARC COMPRESIE 55 BUC
1 14.00 14.00 2.66 16 267735-8 SAIBA 45 BUC 1 15.90 15.90 3.02 17 286250-3 CAPAC
SISTEM PRINDERE BUC 1 19.00 19.00 3.61 18 323771-5 SISTEM PRINDERE BUC 1 21.00 21.00
3.99 19 416568-0 CAPAC MANDRINA BUC 1 31.00 31.00 5.89 TOTAL PIESE =875.96 lei fara
tva MANOPERA 84 LEI FARA TVA TOTAL 959,96 EI FARA TVAMOTOCOASA MAKITA 4T EBH252U
Defectele produsului adus la reparat: FILTRU AER - IMBACSIT, PREFILTRU - IMBACSIT, FILTRU
BENZINA - IMBACSIT, CARBURATOR - DEFECT, BUJIE - ARSA, FURTUN BENZINA - RUPT 1 168497-
0 CARBURATOR BUC 1 168.00 168.00 31.92 2 443141-3 ELEMENT FILTRANT BUC 1 16.80
16.80 3.19 3 443140-5 ELEMENT FILTRANT BUC 1 16.80 16.80 3.19 4 168534-0 BUJIE C