
Reparatii sistem alimentare cu apa

I.D.: 43277414

Data publicarii	27.02.20	Coduri CPV	39370000-6
-----------------	----------	------------	------------

Pretul estimativ:	6.554,00 RON - 6.554,00 RON
-------------------	-----------------------------

Descriere:	Suduri la pozitie coloana teva Ol 2 1/2", bransamente, montat teava PE
------------	--
