
Reetansat reductor cutie viteze

I.D.: 42393321

Data publicarii	02.04.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 2.307,15 RON - 2.307,15 RON

Descriere: REPARATIE CUTIE VITEZE PENTRU AUTOSPECIALA MERCEDES BENZ AXOR 1828 VL - 06 - ACV
GARNITURA = 1 x 101,12 ORING (KDM) = 1x 18,53 GARNITURA = 1 x 10,69 ORING = 1 x 19,11
INEL ETANSARE PRIZA CV = 1x 158,57 CURATITOR FRANA 600 ml = 1 x 10 CURATITOR FRANA
600 ml = 1 x 10 COLIER PLASTIC NEGRU 360 x 7 = 10 x 0,83 COLIERE PLASTIC NEGRE-FASE =
5 x 0,87 ULEI 80W BLAT 234.1 = 13 x 30,55 MANOPERA: D/R CUTIE VITEZE 18 ORE x 80
LEI/ORA VERIFICARE REETANSAT CAPAC REDUTOR = 3 ORE x 80,00 LEI/ORA TOTAL : 2.307,15
LEI FARA TVA
