

Reparatii INFUSOMAT SPACE seria 34358, PERFUSOR COMPACT PLUS seriile 14796 si 14803

I.D.: 81680347

Data publicarii 02.05.23 Coduri CPV 50000000-5 50420000-5

Pretul estimativ: 4.725,17 RON - 4.725,17 RON

Descriere: Reparatii INFUSOMAT SPACE seria 34358, PERFUSOR COMPACT PLUS seriile 14796 si 14803
INFUSOMAT SPACE seria 34358 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA
VALOARE LEI FARA TVA PIESE SCHIMB 34502001 Lump Sum for Consumables (Kit consumabile) 1 50.00 50.00 34521470 OPERATING UNIT (COMPLETE) ISPS (Panou operare ISP) 1 1202.27 1202.27 34521364 FRONT FRAME ISPS (Panou frontal ISP) 1 192.45 192.45 34521356 MEMBRANE ISP (Membrana ISP) 1 83.46 83.46 34520856A AKKUMODUL SP PIN (Acumulator cu pin SP) 1 547.43 547.43 34774386 COVER CAP CASE SP (Capac protectie suruburi SP) 10 1.04 10.40 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 · PERFUSOR COMPACT PLUS seria 14796 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 34522113 Processor board PCP (placa de baza PCP) 1 997.02 997.02 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 · PERFUSOR COMPACT PLUS seria 14803 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522103 HOUSING, UPPER PART PCP (Carcasa partea superioara PCP) 1 567.78 567.78 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 34522000 POWER SUPPLY CP (alimentator CP) 1 264.96 264.96 SERVICII REPARATII MA