

---

## Piese reparatie SONY HSC-100R

I.D.: 44357401

---

Data  
publicarii 24.10.19

Coduri CPV 32350000-1

---

Pretul  
estimativ: 37.567,00 RON - 37.567,00 RON

---

Descriere: 1. SONY SPARES A2107936A (A1974805A) CCD BLOCK ASSY (RP)(CED) 31 081,00 1 2. SONY SPARES 413844402 PANEL, FRONT (1M) 890,00 1 3. SONY SPARES 370150500 SETSCREW 3X3 4,00 1 4. SONY SPARES X23483381 COVER ASSY, HANDLE 429,00 1 5. SONY SPARES X23483331 SUB ASSY, HANDLE 2 013,00 1 6. SONY SPARES X23483313 SUB ASSY, MAIN CHASSIS 3 150,00 1

---