
Reparatie Dacia Duster

I.D.: 84398428

Data publicarii	05.07.23	Coduri CPV	50112100-4 50112000-3
-----------------	----------	------------	-----------------------

Pretul estimativ:	371,88 RON - 371,88 RON
-------------------	-------------------------

Descriere:	Reparatie Dacia Duster: inlocuire supapa comanda turbo, tester
------------	--
