

Materiale reparatii camera centrala termica

I.D.: 91125548

Data publicarii 18.12.23 Coduri CPV 44190000-8

Pretul estimativ: 40.960,49 RON - 40.960,49 RON

Descriere: eps ct 80 g20=0.75mc*231.9328, polifix=15saci*21.8487,plasa ext 160=100mp*2.9412, diblu polistiren 70=250*0.2521, profil pvc cu olasa 2.5m=7*10.9244, doza 2p 24231=3buc*2.1008,doza ramificatie 150*100*60=1*3.3613,burghiu sds 10*160=1*10.084,plinta smart =10buc*13.4454,parchet 10mmstejar=20.774*54.6218,isomaster xps 2cm =31.9*10.9244,mortar tinci ceradez 25kg=8*28.1513,trafalet acril 250=1*22.6891,gratar 265*285=1*2.9412pensula 60=2*5.8824, surub cu diblu 60*60=100buc*0.1261,maner telescopic 3m=1*26.8908, priza dubla zena alb 2*13.0252, intrerupator dublu zena alb =1*10.0840, element imbinare smart =4*2.0168, colt exterior smart =5*2.0168, terminatie smart =2*2.0168, disc inox 230*1.9 =2*8.4034,folie latime 4m=100*1.5966, pensula maner lung 90mm=2*6.3025banda mascare 50*45=2*10.084, tenc mozaicata 25kg=5*268.9076,caparol puzgrund 25kg=2*243.6975,tv 100*100*3=5*235.2941,electrozi 2.5=4.5kg*23.5294, electrozi 3.25=4.5kg*24.3697,disc inox 230*1.9=3*8.4034,disc inox 125*1.2=3*5.042, ciment =40saci*24.7899, plasa sudata de 8=6*357.1429,boltari20*40*20=20buc*5.4622,palet ciment =1*95lei, tub samota 30=22*185.2941, invelis beton 30=26*176.4706,vata minerala 30=52*30.1092,colector condens 30=1*815.1261,grilaj ventilatie 30-45=1*61.1933,usita curatare 12-30=1*479.2353, coltar placa frontala =4buc*7.2269, vata minerala 30=2*30.1681,deflector uni 30=1*218.4874,racord usita curatare =1*1002.2521,racord fum30=1*1069.6387,chit special rapid =10*63.4454,mortar ptr invelis beton =3*50, placa