

Achizitie servicii reparatii motocoasa

I.D.: 90832315

Data publicarii	14.12.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.434,46 RON - 1.434,46 RON

Descriere: Reparatii motocoasa Stihl constand in inlocuire capac carter vibrochen MS 231, 251 1X43.70; rulment cu bile MS 340, 360, 360, 440, 460, 461 2X52.94; piston 41.5 mm MS 231 1X273.11; rulment cu ace 10x14x12.5 MS 231 1X27.73; semering 15x25x5 MS 231, 251, 271, 291 2X44.54; carburator WTF-2 (1,2,4,5) MS 231, 251 1X252.10; manopera 3X84.03; roata lant 3/8" Picco 6Z (1-6) MS 231, 241, 251 1X71.43; rulment ace MS 170, MS 180 1X23.53; lant Stihl 40cm 55p 3/8 1,3 1X58.82; sina STIHL 40CM 1,3 3/8 PI 1X172.27; ulei amestec rosu STIHL 1 L 1X42.02; pila rotunda STIHL 4,5 x 200 mm 2X7.57 si pila rotunda STIHL 5,2 x 200 mm 2X7.56. TOTAL: 1434.46 RON
