
Reparatie pompa la Putul din Comuna Reditu

I.D.: 48326773

Data publicarii	22.07.20	Coduri CPV	42124290-3
-----------------	----------	------------	------------

Pretul estimativ:	3.946,00 RON - 3.946,00 RON
-------------------	-----------------------------

Descriere:	Reparatie pompa Wilo Helix V 1609 conform deviz
------------	---
