
Reparatie Stihl Motocoasa FS 360

I.D.: 85250962

Data
publicarii 26.07.23

Coduri CPV

50800000-3

Pretul
estimativ: 217,56 RON - 217,56 RON

Descriere: Stihl Bujie NGK 4007011-1 buc,14.6218 lei Stihl Filtru Aer 41471410300-1 buc,30.67226 lei
Stihl Set Piese Carburator 41470071700-1 buc,71.42857 lei lucrari service -100.8403 lei
