
Reparatie Emondor - HT 101

I.D.: 44820484

Data publicarii	12.03.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 290,76 RON - 290,76 RON

Descriere: Reparatie Emondor de inaltime STIHL HT 101: pompa ulei, furtun, sorb ulei, snec, sorb combustibil, bujie, semeringuri, curatitor si manopera
