
Reparatie sonda ultrasunet GSW-4/1/SN:04/M1/AT

I.D.: 75920656

Data publicarii	22.11.22	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ:	782,43 RON - 782,43 RON
-------------------	-------------------------

Descriere:	Reparatie Sonda ultrasunet GSW-4/1/SN:04/M1/AT (inlocuire cablu,P-laca de baza si caP-emitator sonda).
------------	---
