
Reparare autovehicul VW Caddy

I.D.: 25973216

Data publicarii	12.02.18	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Termenul limita pentru depunere:	14.02.18	Pretul estimativ:	5.500,00 RON
----------------------------------	----------	-------------------	--------------

Descriere: Reparare autovehicul VW Caddy - Manopera aprox 19-20 ore: inlocuire Volant 1buc, kit ambreaj 1 buc, biela antiruliu spate 2 buc, bucsa bara stabilizatoare 2 buc, amortizoare spate 2buc, bujie incandescenta 4 buc, rulment tren fix cutie viteza 2 buc, releu bujii incandescente 1 buc, Diagnoza si verificare; - Piese de schimb: Volant 1buc, kit ambreaj 1 buc, biela antiruliu spate 2 buc, bucsa bara stabilizatoare 2 buc, amortizoare spate 2buc, bujie incandescenta 4 buc, rulment tren fix cutie viteza 2 buc, releu bujii incandescente 1 buc;
