
Reparatie amambulanta VW Transporter - inlocuit motor si schimbat distributie la ambulanta VW Transporter cu numarul de inregistrare MAI 33869. SS: WV1ZZZ7HZCH056106

I.D.: 15509513

Data publicarii	13.10.16	Coduri CPV	50200000-7
-----------------	----------	------------	------------

Termenul limita pentru depunere:	17.10.16	Pretul estimativ:	19.186,00 RON
----------------------------------	----------	-------------------	---------------

Descriere:	Reparatie amambulanta VW Transporter - inlocuit motor si schimbat distributie la ambulanta VW Transporter cu numarul de inregistrare MAI 33869. SS: WV1ZZZ7HZCH056106
------------	---
