
Reparatie amambulanta VW Transporter - inlocuit motor si schimbat distributie la ambulanta VW Transporter cu numarul de inregistrare MAI 33869. SS: WV1ZZZ7HZCH056106

I.D.: 15509513

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 13.10.16 | Coduri CPV | 50200000-7 |
|-----------------|----------|------------|------------|

| | | | |
|----------------------------------|----------|-------------------|---------------|
| Termenul limita pentru depunere: | 17.10.16 | Pretul estimativ: | 19.186,00 RON |
|----------------------------------|----------|-------------------|---------------|

| | |
|------------|---|
| Descriere: | Reparatie amambulanta VW Transporter - inlocuit motor si schimbat distributie la ambulanta VW Transporter cu numarul de inregistrare MAI 33869. SS: WV1ZZZ7HZCH056106 |
|------------|---|
