
Reparatie masina de spalat DHB-70

I.D.: 84956372

Data publicarii	20.07.23	Coduri CPV	50882000-1
-----------------	----------	------------	------------

Pretul estimativ: 7.791,00 RON - 7.791,00 RON

Descriere: Reparatie masina de spalat DHB-70- Inlocuire piese, manopera si deplasare: 12220185 Usa tambur 1 buc 12227048 Rezistenta 6kW 3 buc ACHIZITIA TINE LOC DE COMANDA FERMA
