
Servicii de reparare masina de spalat si uscator Electrolux

I.D.: 106311077

Data publicarii	29.11.24	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.000,00 RON - 1.000,00 RON

Descriere: Reparatie masina de spalat rufe Electrolux ,inlocuit pompa evacuare apa,inlocuit electrovalva, Uscator Electrolux inlocuit role cu rulment sustinere tambur la DGASPC SECTOR 1/ CSS.Pinocchio
