
Servicii de reparatii auto - Mercedes Sprinter

I.D.: 74655493

Data publicarii	24.10.22	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 801,12 RON - 801,12 RON

Descriere: Inlocuit etrier fata stg. 1.0x 75.63 = 75.63 lei Inlocuit suport cardan 2.0x 75.63 = 151.26 lei
Etrier reconditionat 1.0x 390.68 = 390.68 lei Suport cardan 1.0x 183.55 = 183.55 le
