
Servicii de reparatie POMPA DAB 1.1KW/3000T

I.D.: 42386795

Data publicarii	01.04.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 490,00 RON - 490,00 RON

Descriere: Servicii de reparatie POMPA DAB 1.1KW/3000T, demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei, diverse
