

Reparatie taietor asfalt si placa vibranta

I.D.: 98019810

Data publicarii 30.05.24

Coduri CPV 50000000-5 50800000-3

Pretul estimativ: 3.905,52 RON - 3.905,52 RON

Descriere: Reparatie debitator STIHL TS800 conform deviz ,Reparatie placa vibranta conform deviz
