
Reparatii electropompa Pedrollo 1.7 kw

I.D.: 38456733

Data publicarii	16.09.19	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 1.265,60 RON - 1.265,60 RON

Descriere: Reparata electropompa Pedrollo 1.7 kw : 1 Conductor bobinaj = 185.50 ron 2 Manopera bobinaj = 105 ron 3 Rulment inferior , 1 buc = 85 ron 4 Rulment superior , 1 buc = 80 ron 5 Kit etansare mecanica superioara = 202.50 ron 6 Kit etansare mecanica inferioara = 375 rpon 7 Kit inele Oring = 136.80 ron 8 Cablu MYYM 4x1.5 mmp , 10 ml = 95.8 ron
