
Reparatie motoferastrau

I.D.: 52944754

Data
publicarii 21.12.20

Coduri CPV

50800000-3

Pretul
estimativ: 782,71 RON - 782,71 RON

Descriere: lant 18" .325 1,5mm 21LPX Buc 3 ulei amestec 1 L Husqvarna LS+ pentru motoare in 2T Buc
4 pila rotunda 4,8mm Oregon Buc 4 filtru carburant Hva Buc 1 sprochet .325" Buc 1 bujie 2T
NGK Buc 1 piulita M8 Buc 1 amortizor cilindru 357xp, 359 Buc 1 flansa partitie 357xp, 359
Buc 1 arc ambreiaj 357xp, 359 Buc 1 MANOPERA UT 15 sina de ghidaj Hva 18" 1,5mm 325
Buc 1
