
Reparatie mixer Wilo, tip Wilo-EMU TR 215.44-4/8

I.D.: 51926435

Data publicarii	24.11.20	Coduri CPV	50500000-0 45259100-8
-----------------	----------	------------	-----------------------

Pretul estimativ: 5.598,80 RON - 5.598,80 RON

Descriere: - Demontat mixer in parti componente, curatat piese demontate; - Efectuat masuratori electrice, dimensionale; Reparatie: - Inlocuit piese de schimb (etansari mecanice, rulmenti, simeringuri, inele O, ulei camera etansare); - inlocuit cablu de alimentare; - Asamblat mixer; - Efectuat proba de functionare.
